

BRUNSING ASSOCIATES, INC.
P.O. BOX 588
Windsor, CA. 95492
Telephone: (707) 838-3027
Fax: (707) 838-4420

BORING NO.: **B-1** SHEET 1 OF 1
PROJECT: **COTATI STATION**
LOCATION: **Cotati, California**
PROJECT NO.: **771**
LOGGED BY: **SMS**

COORDINATES:

SURFACE ELEVATION:

DATUM:

SAMPLE INFORMATION						DESCRIPTION	STRATA	WELL CONSTRUCTION DETAIL
DEPTH FEET	LAB SAMPLE	SAMPLE TYPE	BLOW COUNTS	Recovery (%)	PID (ppm)			
5			12 11 11		0.0	DARK BROWN-BLACK CLAY (CL) dry to moist, stiff, ~5% gravel, ~95% clay, angular gravel up to ~22mm		5
10			5 5 8		0.0	BROWN CLAY (CL) moist, soft to medium stiff, ~5% coarse-grained sand, ~10% silt, ~85% clay		10
15			19 22 30		5.0	DARK BROWN-GREENISH BROWN SANDY GRAVEL (GC) moist, medium dense, ~40% gravel, ~30% very coarse to medium-grained sand, ~10% silt, ~20% clay, subrounded gravel up to ~14mm		15
20			8 11 11 6 7 7		0.0	GRAVEL (GP) wet, loose, ~90% gravel, ~10% silt, angular gravel up to 16mm (possible backfill material?)		20

DRILLING CONTRACTOR: Clear Heart

DRILLING METHOD: 6-inch hollow stem auger

DRILLING EQUIPMENT: Deeprock Dr10K

DRILLING STARTED: 11/22/04 ENDED: 11/22/04

REMARKS Boring drilled to 20.0' BGS.
Sampler driven to 23.0' BGS

See key sheet for symbols and abbreviations used above.



BRUNSING ASSOCIATES, INC.

Job No.: 771

Appr:

Date: 2/10/05

LOG OF BORING B-1

COTATI STATION
8348 Santero Way
Cotati, California

PLATE

4